0CS-Y-0181



United States Department of the Interior

MINERALS MANAGEMENT SERVICE Alaska Outer Continental Shelf Region 3801 Centerpoint Drive, Suite 500 Anchorage, Alaska 99503-5823

MAR 2 3 2007

Craig Wiggs Northstar/Endicott/Badami, Delivery Manager BP Exploration (Alaska) Inc. P.O. Box 196612 Anchorage, Alaska 99519-6612

Dear Mr. Wiggs

While reviewing our records for the Northstar Unit, we realized that the Minerals Management Service (MMS) had not formally responded to BP Exploration (Alaska) Inc, (BPXA's) letter on July 11, 2006 requesting a change in status for the Northstar Reservoir from sensitive to nonsensitive oil-with-associated-gas-cap reservoir. The MMS had previously advised BPXA verbally that we did not agree with the proposed re-designation. As provided for under 250.1107(c) "Enhanced oil and gas recovery operation" all appropriate forms and data submittals are still required including form MMS-127 SRI.

Sincerely,

Jeff Walker Regional Supervisor Field Operations

cc: John K. Norman, Chairman, Alaska Oil and Gas Conservation Commission

